



Aerial inspection of warehouse roof for client, could not be accessed by MEWP due to access restrictions and ground conditions.

Locations: London, Leeds and Nottingham

Equipment used: Phantom 4

Brief: aerial inspection of roof channels and roof “mansafe” system, HD video and photography of any areas of concern. Live feed to ipad display to allow additional focus on areas of concern at time of flight.

Additional issues: London location with Class D airspace and in proximity to airport. Liaison with air traffic control and NATS to agree works. Full RAMS and site information pack submitted to client prior to work commencing, CSCS card required for site induction.

Full pedestrian access of flight area managed by on site team and safety distances observed.

Time taken ~20 minutes flying time per site









